





12726 Roswell Ave Chino, CA 91710  
909 627-2697 Fax 909 591-1243

The backflow preventers in Cibola are starting to need work. In an effort to keep costs down and to expedite repairs, I have attached a price list for repairs if needed at the time of testing. These prices are only valid at time of testing. If you choose not to pre- approve repairs, cost to repair will be higher. If the device is not serviceable, I will contact you for approval prior to replacement.

# Common Repair Costs

Clean & retest.....	\$85.00
Clean, rebuild, & retest 975XL 1" or 3/4 device.....	\$255.00
If seats are needed add .....	\$25.00 per seat
Brass Test cock replacement.....	\$28.00 ea

**Pre- Approval:** (only if repairs are needed)

I hereby approve the above repairs if deemed as needed by the test results of the initial test. Repair costs will be billed and due upon completion of repairs. I will be contact you for approval prior to commencement of work if device needs to be replaced. Please provide payment info.

**Print Clearly**

Approved By: \_\_\_\_\_

Print Name: \_\_\_\_\_

Ph: \_\_\_\_\_

If 3/4 or 1" device is not serviceable and needs replacement...\$1175.00